










TEMPO




Teil	Pcs	Colli
1	1x	1/4
2	1x	2/4
3	1x	3/4





A	B	C	D	E	F	G
						
5x	5x	2x	20x	2x	2x	2x
H-140	H-140	H-50	5x30		M6X15	M6X15

1






2



F	G	E
		
2x	2x	2x
M6 X 15	M6 X 15	

3






A	B	C	D
			
2x	2x	2x	8x
H-140	H-140	H-50	5x30

L

4

R





A	B	D
		
1x	3x	4x
H-140	H-140	5x30

L

5


R




A  2x	D  8x
H-140	5x30

6

L



R



7

