







x2





<p>A</p>  <p>Ø 8x30 12</p>	<p>B</p>  <p>8</p>	<p>D</p>  <p>5</p>	<p>I</p>  <p>8</p>
--	---	---	---




II

<p>a</p> <p>Ø 8x30 4</p>	<p>B</p> <p>2</p>	<p>D</p> <p>5</p>	<p>S</p> <p>4</p>	<p>Filz</p> <p>4</p>
------------------------------	-------------------	-------------------	-------------------	----------------------




<b>D</b>		
		2
<b>A1</b>		∅ 8x20
<b>A</b>		10
		∅ 8x30
		2




1°






2°



3°








IV



V



<p>H</p>  <p>Ø 3x16 5</p>	<p>N</p>  <p>14</p>	<p>P</p>  <p>5</p>
--	--	---






VII

Z	E	O	J
12	4	OL1/OR1	8



VIII

B	D	L	M	R
4	4	4	1	2



f

