





# BETT 0568 - MONTAGEANLEITUNG

|   |                     |    |
|---|---------------------|----|
| 1 | Rechte Seiten       | 1× |
| 2 | Linke Seiten        | 1× |
| 3 | Kopfseite           | 1× |
| 4 | Fußseite            | 1× |
| 5 | Polster kopfteil    | 1× |
| 6 | Mittelträger leiste | 1× |
| 7 | Querträger leisten  | 2× |
| 8 | Kopfteil träger     | 2× |
| 9 | Stahl Fuss          | 1× |




40 Minutes






|                                                                                                       |                                                                                                         |                                                                                                       |                                                                                                     |                                                                                                     |                                                                                                       |                                                                                                           |                                                                                             |                                                                                               |
|-------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|
| 6x15<br><br>A x 8  | <br>C x 2            | M8x20<br><br>D x 2 | M 8<br><br>E x 4 | M 8<br><br>F x 2 | M6x40<br><br>G x 4 | 10x40<br><br>I x 4   |                                                                                             |                                                                                               |
| M6x65<br><br>J x 4 | M6,3x60<br><br>K x 4 | <br>L x 6          | <br>M x 6        | <br>N x 1        | <br>O x 2          | 3,5x16<br><br>P x 42 | 13<br> | SW 4<br> |

1.

DETAIL A






DETAIL B





2.

DETAIL A







3.





4.











5.



6.



7,



8,

