





TWO

54-122-..-M














54-122-E5 ☐

54-122-17 ☐





90min



L=932mm  J53 1	6,5/68mm  O4 2	±10x50mm  O7 2	±4.0x30mm  P8 4	L  K25 1	R  K26 1	±5/16mm  J3 24	±3.5x13mm  P5 12	H=2  H4 6								
									±15/12mm  C 8	L=20mm  D2 8	±8x30mm  A 16	 E 8	 L 10	±3.0x16mm  P11 10	 L2 10	±35/9mm  G1 6


1-LFR-14

ISM-LFR-14




Colli	Ersatzteil Nummer	Dimension
Colli 1/1	LFR.101	663x175x16
	LFR.102	663x175x16
	LFR.213	1002x225x16
	LFR.310 x4	303x140x16
	LFR.302 x2	327x140x16
	LFR.407	968x174,5x16
	LFR.501	631x152x16
	LFR.502	631x152x16
	LFR.622	640x316x2,5
	LFR.629	640x316x2,5
	LFR.604	640x341x2,5
	LFR.719 x2	659x324x19
	LFR.704	659x340x19

1









2

15/12mm	C
4	
5/16mm	J3
16	
8x30mm	A
8	








3

$\varnothing 15/12\text{mm}$	$L=20\text{mm}$	$\varnothing 8 \times 30\text{mm}$
		
C	D2	A
2	6	4




4


$\varnothing 3.5 \times 13\text{mm}$	$H=2$	$\varnothing 35/9\text{mm}$
		
P5	H4	G1
12	6	6




5








6




7








8





		
L	P11	L2
10	10	10

3.0x16mm

9





6,5/68mm	10x50mm
O4	O7
2	2

