




JAPAN assembly

JAPAN CORNER



NB! First turn all 3 screws half way by hand and then continue with the Allen key.

