












	L	W	H	Pcs
1	163	123	55	1x
2	193	123	55	1x


R



L





A  5x	B  6x	C  2x	D  12x	E  10x	F  1x	G  1x	H  12x	I  15x
H-170		H-170	M6	M6 X 60	M6 X 70	M6 X 45	M6 X 25	5X30
J  1x	K  58x51 2x	L  74x51 1x	M  53x33 2x					



B	H
	
6x	12x
M6 X 25	





1


R






L





A	C	D	E	F	G	I	J
							
2x	2x	6x	4x	1x	1x	6x	1x
H-170	H-170	M6	M6 X 60	M6 X 70	M6 X 45	5x30	









A	D	E	I
			
3x	6x	6x	9x
H-170	M6	M6 X 60	5x30





4





4

