

























KINT02








KINT02

A1 8 x 35 mm x34 	A6 8 x 24 mm x4 	C2 5 x 13 mm x4 
E0 Ø16 x10 	E1 15 x 12 mm x16 	F1 6 x 34 mm x16 
G1 7 x 50 mm x12 	I2 4 x 16 mm x16 	I4 3,5 x 27 mm x7 
M  x1	N5 3,5 x 16 mm x8 	O14 + O13  x2
O16 + O13  x2	P28  L - 450 mm x1	T12  L - 450 mm x1
TZ  L R x1		




KINT02




1	1100	650	22	x1	2/2
2	1100	650	22	x1	2/2
3	326	610	16	x1	2/2
4	326	610	16	x1	2/2
5	326	610	16	x1	1/2
6	668	326	16	x1	1/2
7	556	60	16	x1	1/2


8	450	200	16	x1	2/2
9	450	200	16	x1	2/2
10	628	186	16	x1	1/2
11	640	455	3	x1	2/2
12	696	320	16	x1	1/2
13	696	320	16	x1	1/2
14	326	80	16	x2	1/2




1 ►





2 ►





3 ►





4 ►





5 ►






6 ▶





7 ▶





8 ▶






9 ▶





a)



b)




c)







13▶






14▶




15▶





16▶



17 ►



18 ►



A=B

