











STRINGTON








			✓
①	1	820x350x16	
②	1	818x357x36	
③	3	818x36x16	
④	1	818x36x16	
⑤	1	820x350x16	

			✓
⑥	6	334x36x16	
⑦	1	820x350x16	
⑧	3	817x317x12	
⑨	3	333x317x12	








A x 12  M6x15 mm	B x 6  M6x55 mm	C x 32  Ø4x12 mm	D x 6  M6/Ø12x15 mm	E x 2  75x30x15 mm
F x 1  4 mm				


1




2





3




4






5





6







7





8




9






10





11





12




13








XX=YY




Ax12
Cx30






14



15



16



17

