






TEMPO





Teil	L	W	H	Pcs	Colli
1	170	120	70	1x	1/4
2	132	116	70	1x	2/4
3	129	110	70	1x	3/4

L








R





4/4




A	B	C	D	E	F	G
						
5x	5x	20x	2x	2x	2x	2x
H-100	H-100	M 3,5/25	H-50	M6 X 15	M6 X 15	


1



2



E



2x

M6 X 15


F



2x


M6 X 15



G






2x


3




A  H-100 2x	B  H-50 2x	C  M 3,5/25 4x	D  H-100 2x
--	--	--	---



C  M 3,5/25 8x	D  H-100 2x
--	--



A  H-100 3x	C  M 3,5/25 4x	D  H-100 1x
---	---	--

