







“3414”

versionsnummer: 16.12.2023














Naturholz kann sich werkstoffbedingt verziehen. Durch das Montieren ziehen sich Teile wieder plan.



B1	
2x  $\phi 8 \times 32$ mm f1	
2x  $\phi 8 \times 40$ mm t14	1x  z1
4x  5x10.5 e3	2x  n3
3x  s1	3x  $\phi 7 \times 70$ mm e9



B2	
3x  g31	2x  $\phi 4 \times 25$ mm j5
1x  g33L	1x  g33R
1x  550 mm g34	8x  $\phi 4 \times 20$ mm j30


1






2

3



- 3x  **g31**
- 1x  **g33L**
- 1x  **g33R**
- 1x  550 mm **g34**
- 8x  $\phi 4 \times 20$ mm **j30**
- 2x  $\phi 4 \times 25$ mm **j5**








4

4

x2

 $\phi 8 \times 40$ mm t14



5