


I.

1

A

M6x13



4x

F

Ø18xØ6x1.5



4x

G

5MM




1x



5

6


X4



2

D


M8x40



4x

H

6MM




1x




1

4




II.

3



C	M6x35
	4x
E	M6
	4x
F	Ø18xØ6x1.5
	4x
G	5MM
	1x
80%	

4





B	M6x30
	4x
F	Ø18xØ6x1.5
	4x
G	5MM
	1x
80%	

III.

5

G		5MM
		1x
		



LE TRI
+ FACILE





Séparez les éléments avant de trier

BAC
DE
TRI