




48292780 48292930 48294640 48293050



WICHTIG - FÜR SPÄTERE VERWENDUNG
AUFBEWAHREN - SORGFÄLTIG LESEN

AVIS - Ces instructions doivent être sauvegardées
Pour utilisation future - Les instructions doivent
être suivies

IMPORTANTE, conservar estas instrucciones
para futuro uso. Siga estas instrucciones atentamente

VIGTIGT - Samlevejledningen skal opbevares
i arkiv til senere brug - Skal gennemlæses nøje

NOTICE - These instructions must be saved
for future use - Instructions must be followed

48292780

TEILCHECKLISTE
LISTE DE CONTROLE
LISTADO DE CONTROL
TJEKLISTE
CHECK LIST

Réf./No.	Réf./Art	Qty./Stck./Quantité	Size / Maß / Dimension (mm)	Packed in box	
1	329755278	1	1800x400x18	2	✓
2	328717278	1	320x354x16	1	
3	328718278	1	320x354x16	1	
4	329756278	1	1800x400x18	2	
5	328720278	2	320x335x16	1	
6	329757278	3	447.5x310x16	1	
7	329758278	1	1394x330x3	2	
8	228703	6	200x50x50	1	
9	329759278	2	1300x330x12	1	

48292930


Réf./No.	Réf./Art	Qty./Stck./Quantité	Size / Maß / Dimension (mm)	Packed in box	
1	329755293	1	1800x400x18	2	✓
2	328717293	1	320x354x16	1	
3	328718293	1	320x354x16	1	
4	329756293	1	1800x400x18	2	
5	328720293	2	320x335x16	1	
6	329757293	3	447.5x310x16	1	
7	329758293	1	1394x330x3	2	
8	228703	6	200x50x50	1	
9	329759293	2	1300x330x12	1	

48294640

Réf./No.	Réf./Art	Qty./Stck./Quantité	Size / Maß / Dimension (mm)	Packed in box	
1	329755464	1	1800x400x18	2	✓
2	328717464	1	320x354x16	1	
3	328718464	1	320x354x16	1	
4	329756464	1	1800x400x18	2	
5	328720464	2	320x335x16	1	
6	329757464	3	447.5x310x16	1	
7	329758464	1	1394x330x3	2	
8	228703	6	200x50x50	1	
9	329759464	2	1300x330x12	1	

48293050









Réf./No.	Réf./Art	Qty./Stck./Quantité	Size / Maß / Dimension (mm)	Packed in box	
1	329755305	1	1800x400x18	2	✓
2	328717305	1	320x354x16	1	
3	328718305	1	320x354x16	1	
4	329756305	1	1800x400x18	2	
5	328720305	2	320x335x16	1	
6	329757305	3	447.5x310x16	1	
7	329758305	1	1394x330x3	2	
8	228703	6	200x50x50	1	
9	329759305	2	1300x330x12	1	



TEILCHECKLISTE - LISTE DE CONTROLE - LISTADO DE CONTROL- TJEKLISTE - CHECK LIST

Réf./No.	Réf./Art.	Qty./Stck./Quantité	✓
A	229760	16	
B	229760	12	
C	229760	12	
D	229760	24	
E	229760	12	
F	229760	1	
G	228705	2	
H	228705	4	

Réf./No.	Réf./Art.	Qty./Stck./Quantité	✓
J	229760	12	
K	229760	12	
N	229760	12	

16 - A  $\varnothing 8 \times 30 \text{mm}$	12 - B  $\varnothing 10 \times 43.5 \text{mm}$	12 - C  $\varnothing 15 \times 11 \text{mm}$	24 - D  $M6 \times 16 \text{mm}$	12 - E  $\varnothing 7 \times 50 \text{mm}$	1 - F  4mm
2 - G  $180 \times 15 \times 7 \text{mm}$	4 - H  $M4 \times 16 \text{mm}$	12 - J 	12 - K  $\varnothing 3 \times 18 \text{mm}$	12 - N  $\varnothing 5 \times 16 \text{mm}$	


Geehrter Kunde.
Hier haben Sie die Möglichkeit die mitgelieferten
Schrauben nachzumessen.

Cher Client.
La règle ci jointe vous permet de mesurer la visserie.

Estimado cliente.
aquí podrá medir la tornillería adjunta.


Kære kunde.
Her har De muligheden for at måle medsendte beslag.

Dear Customer.
Below you have the opportunity to measure the
Enclosed Hardware.




1

16 - A




2


12 - B




3

12 - C






4



5

12 - E


1 - F



6


12 - J

12 - K




7

24 - D




1 - F







8


2 - G




4 - H









9




10



11




12




13

12 - N



14



15

