


Montageanleitung 60631

 20 MIN



1. SCREW




2 PC.

2. STUCK DRILL



2 PC.



Belastbarkeit maximal 10KG