


SERVICEKARTE/SERVICECARD

Modellname/Modelname: BE-0823


Ausführung: wildeiche massiv geölt
Finishing: solid oiled wild oak

Modellnummer:
1014825




140x200

Modellnummer:
1014829




140x200

Modellnummer:
1014833




140x200

Modellnummer:
1014826




160x200

Modellnummer:
1014830




160x200

Modellnummer:
1014834




160x200

Modellnummer:
1014827




180x200

Modellnummer:
1014831




180x200

Modellnummer:
1014835




180x200

Modellnummer:
1014828




200x200

Modellnummer:
1014832




200x200

Modellnummer:
1014836



200x200

71306



DE: Sehr geehrter Kunde, Sehr geehrte Kundin!

Fehlt Ihnen ein Beschlagteil oder ist es Defekt? Kein Problem! Nutzen Sie unsere Servicekarte!

Unser Direkt-Bestellservice für fehlende/defekte Beschlagteile:

Kontaktieren Sie uns telefonisch unter Tel. +499503/5033-114 oder senden Sie uns eine E-Mail an kundendienst@3s-frankenmoebel.de.

Bitte geben Sie dabei folgende Pflicht-Informationen an: -> Auftragsnummer, Artikelnummer, Nummer des Beschlagteils, fehlende/defekte Menge, und den Grund der Beanstandung, ob es sich um ein defektes oder fehlendes Beschlagteil handelt. Tragen Sie die benötigte Menge ein. Mailen Sie uns die vollständig ausgefüllte Servicekarte zu, um die Bearbeitung zu ermöglichen. Für andere Beanstandungen / Beschädigungen an Ihrem Möbelstück wenden Sie sich bitte direkt an Ihr Möbelhaus.

EN: Dear customer!

Are you missing a fitting part or is it defective? No problem! Use our service card!



Our direct ordering service for missing/defective fitting parts:

Contact us by telephone on +499503/5033-114 or send us an e-mail to kundendienst@3s-frankenmoebel.de.

Please include the following mandatory information: -> Order number, article number, number of the fitting part, missing/defective quantity, and the reason for the complaint, whether it is a defective or missing fitting part. Enter the required quantity.

Mail us the completed service card to enable processing.








For other complaints/damage to your furniture, please contact your furniture store directly.

						M6x20  L x 8	SW 4 	SW 5 	Filz Felt  K x 4
3,5x16  A x 54	 B x 8	Ø10x40  C x 12	8x35  D x 12	M6x50  E x 12	M6x75  F x 4	M6x30  G x 4	 H x 8	 I x 2	 J x 2

Grund der Beanstandung/Reason for appeal.....

Name/Name:.....Telefon/Phone:.....

PLZ/Place:.....Ort/Location.....Hause-Nr./Home-Nr.:.....


				
				
				




BETT/BED 0823, 0824, 0825 MONTAGEANLEITUNG/ASSEMBLYINSTRUCTIONS




40 Minutes




7




7a



7b




5a



14

0823

5b




15

16

0824

5c



9

10

11

0825



M6x20

Lx8



M6x20

Lx6



Ø10x40

Cx6



35x35x90

Mx2



3,5x16

Ax12



Ø10x40

Cx4



8x35

Dx2



M6x50

Ex4



M6x30

Gx4



SW 4




SW 5




Filz
Felt

Kx4

3,5x16




Ax54



Bx8

Ø10x40



Cx12

8x35



Dx12

M6x50



Ex12

M6x75




Fx4

M6x30



Gx4



Hx8




Ix2



Jx2


1+2

1.




3,5x16		Ø10x40	8x35	M6x50	SW 5
					
Ax24	Bx6	Cx8	Dx4	Ex4	

2.




3,5x16		M6x75	SW 4	Filz Felt	Ø10x40
					
Ax4	Bx1	Fx4		Kx2	Cx4

3.




8x35  Dx4	M6x50  Ex4	SW 5 
---	--	--

4.




3,5x16  Ax4	 Bx1	8x35  Dx4	M6x50  Ex4	SW 5 
--	--	--	---	---

5a.




M6x20	SW 4	Filz Felt	8x35	M6x50
L x 8		K x 2	D x 4	E x 4

5b.




M6x20	Ø10x40	SW 4	3,5x16	35x35x90
L x 6	C x 6		A x 12	M x 2

5c.




Ø10x40  Cx 4	8x35  Dx 2	M6x50  Ex 2	SW 5 	Filz Felt  Kx2	M6x30  Gx4
--	--	---	--	--	--


6.




7



7a




7b



M6x30  Gx4	SW 4 
---	---

7.



8.

